

Corrigendum

to

ACER IMPLEMENTATION MONITORING REPORT OF THE NETWORK CODE ON REQUIREMENTS FOR GRID CONNECTION OF GENERATORS

Second Edition

Document history

Version	Comment	Date
1	Original version available at: https://www.acer.europa.eu/Official_documents/Acts_of_the_Agency/Publication/Second%20ACER%20Implementation%20Monitoring%20Report%20of%20the%20Network%20Code%20on%20Requirements%20for%20Grid%20Connection%20of%20Generators%20-%20original%20version.pdf	27 November 2019
1.1	Corrigendum The corrigendum rectifies the first sentence in Paragraph 87. The change is set out below.	18 December 2019

Changes from Original to Corrigendum version (December 2019)

The change (indicated in *italics*) introduced a negation (*‘not’*) in the first sentence of Paragraph 87. This clarifies that the national Regulatory Authorities do not have the responsibility of ensuring the existence of Authorised Certifiers, which had been wrongly ascribed to them in Version 1.

5.1 Objectives

The first sentence of Paragraph 87 has been changed as follows:

Version 1	Corrigendum 1.1
“It is to be noted that it is the responsibility of the NRAs to ensure the existence of an Authorised Certifier able to produce and validate EqCs for the PGM installations in its MS”	“It is to be noted that it is <i>not</i> the responsibility of the NRAs to ensure the existence of an Authorised Certifier able to produce and validate EqCs for the PGM installations in its MS”